

FIG. 1




FIG. 2




FIG. 3

FIG. 4




FIG. 5





FIG. 6






FIG. 7

FIG. 8

TangoPoint.com

Inspections

Inspector: Facility Manager

Building: KSOPHF

Address: 6200 Sprint Parkway, Overland

Location: 1st Floor

Date: 6/6/2000

Inspection Type: Weekly

Start Inspection **Exit**

(a)

Weekly Inspection Form

Add/Edit **Close**

- ☒ **Food Service Inspection**
 - Signage, prices, labels correct and price
 - Food preparation surfaces clean
 - Kitchen hood and filters clean
 - Silverware and trays clean/dry
 - Manager on duty during food service
 - pest control logs updated and used
- ☐ Janitorial Inspection
- ☐ Help Desk Inspection
- ☐ Irrigation System Inspection
- ☐ Landscaping Inspection
- ☐ Pest Control Inspection
- ☐ Restrooms Inspection
- ☐ Trash Removal/Recycling Inspection

(b)

Weekly Inspection Form

Save **Cancel**

Food Service Inspection

Signage, prices, labels correct and price

Question 1 of 6

9.0-10.0= Good 6.0-8.0= Satisfactory 3.0-5.0= Marginal 0.0-2.0= Poor

Rating: 2

Comments: Correlative Action

Direction: Lewis Hall Room: 1

What: Carpet

Action: Spot Clean

Notes: Remove the Stains

(c)

Notes

☐ Mail this as an attachment

To: John@ABCcleaningco.com

Cc: Victor@ABCcleaningCo.com

Sub: Carpet cleaning in Lewis Hall


Hi John;


We would like to have the carpet in Lewis hall clean and get rid of the stains .

Jimmy

Save **Clos**

(d)












FIG. 11













FIG. 16






FIG. 18






FIG. 19








FIG. 22 (a)




FIG. 22 (b)




FIG. 22 (c)





FIG. 23




[illegible]

FIG. 24 (b)




FIG. 25




FIG. 26

36

